## INSTALLATION INSTRUCTIONS

## **TRUSS/POLE KIT**

## TPK-3

The TPK-3 includes four clamps for 0" – 1" OD round or square poles.


## WARNING: IMPROPER INSTALLATION MAY RESULT IN SERIOUS PERSONAL INJURY!

When mounting Chief Manufacturing accessories, the structural system and mounting method **MUST** be capable of supporting 5 times the combined weight of the total installation. The maximum weight to be installed on the clamps is 150 pounds (68.04Kg) for the set.

Washer

Unpack and check contents:

- (4) CLAMP, 0" 1"
- (8) BOLT, hex head, tap, 3/8-16 X 1 1/4"
- (8) WASHER, flat, 3/8"



Bolt

1. Place clamp (see Figure 1) on truss or pole (see Figure 2).

Clamp

- Using two 3/8-16 X 1 1/4" hex head bolts and 3/8" flat washers, secure clamp to device being mounted (SEE WARNING ABOVE).
- 3. Repeat Step 1 and Step 2 for the second clamp.
- 4. Repeat Step 1 and Step 2 for the third clamp.
- 5. Repeat Step 1 and Step 2 for the fourth clamp.




Figure 2. TPK-3 Truss Mount Example



CHIEF MANUFACTURING INC. 1-800-582-6480 952-894-6280 FAX 952-894-6918 12800 HIGHWAY 13 SOUTH, SUITE 500 SAVAGE, MINNESOTA 55378 USA 8807-000006 2003 Chief Manufacturing <u>www.chiefmfg.com</u> 06/03